



VOLKSWAGEN SHARAN: 1KAL093

Vinnnumber:	WVWZZZ7NZFV032330	Versionname:	2.0 CR TDI 103KW COMFORTLINE BMT
First Registrationdate:	19/03/2015	Fiscalpower:	
Expertise Mileage:	124964	Power Kw:	103
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3619
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/92 H LightMetal				
Summer tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Total cost ex VAT	1289,57
Rocker panel inner R L, Scratch(es), Forfeit	115,56



Roof, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Windscreen, Scratch(es), E - Replace 560,64



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00



Wing F L, Dent(s), LI - Repair and paint (complete) 264,21



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display