



FORD Focus: 1GKX447

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | WFOLXXGCBLEY11166 | Versionname: | FOCUS CLIP. ECONetic Trend 88g 105PK |
| First Registrationdate: | 6/03/2014 | Fiscalpower: | |
| Expertise Mileage: | 137974 | Power Kw: | 77 |
| Bodytype: | Break | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1709 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Luggage cover |
| Windows electric F | Rear parking sensors |
| Cruise Control | Type of Tow bar |
| Steering wheel multifunctional | No Tow bar |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------|-------|------------------------|-------|------------------------|
| 205/55/16/91 V Steel | | | | |
| Summer tyres: | Fr.L. | Uniroyal: 8 mm | Fr.R. | Uniroyal: 8 mm |
| | Re.L. | Firestone: 4 mm | Re.R. | Firestone: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

Total cost ex VAT 496,30

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80





| | |
|---|--------|
| Maintenance book, Missing, E - Replace | 0,00 |
| <i>No pictures to display</i> | |
| Door F R, Scratch(es), 67 - Polish | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper corner R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing F L, Scratch(es), LI - Repair and paint (complete) | 220,18 |



| | |
|------------------------------------|-------|
| Seat cover F L, Hole, Smart repair | 64,32 |
|------------------------------------|-------|



| | |
|----------------------------------|------|
| Bonnet, Scratch(es), 67 - Polish | 0,00 |
| <i>No pictures to display</i> | |
| Roof, Scratch(es), 67 - Polish | 0,00 |
| <i>No pictures to display</i> | |