



BMW 2 Active Tourer: VF5597

Vinnumber:	WBA2C51060V387357	Versionname:	2 ACTIVE TOURER 220dXA 190PK Aut.
First Registrationdate:	8/05/2015	Fiscalpower:	
Expertise Mileage:	60709	Power Kw:	140
Bodytype:		Body color:	Beige
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4719
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Windows electric F		Seats electric F L	
Windows electric R		Seats electric F R	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/91 W LightMetal			
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Hankook: 4 mm	Re.R.	Hankook: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	190,00
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Door R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display