



AUDI A4: 1HAB005

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------|
| Vinnumber: | WAUZZZ8K6EN044034 | Versionname: | A4 BER TDie 136PK |
| First Registrationdate: | 2/06/2014 | Fiscalpower: | |
| Expertise Mileage: | 71582 | Power Kw: | 100 |
| Bodytype: | Berline | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4508 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|----------------------------------|----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Rear parking sensors | |
| GPS storage | HD | Type of Tow bar | No Tow bar |
| Windows electric F | | | |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining artificial leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 205/60/16/92 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 692,88 |
|-------------------|---------------|

| | |
|-------------------------------|-------------|
| Tailgate, Dent(s), Acceptable | 0,00 |
|-------------------------------|-------------|

No pictures to display

| | |
|-------------------------------|-------------|
| Door R L, Dent(s), Acceptable | 0,00 |
|-------------------------------|-------------|

No pictures to display

| | |
|-----------------------------------|-------------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

Bumper F, Deformed / Strained, Le - Replace and paint 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Outer door handle R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Bonnet, Dent(s), LI - Repair and paint (complete) 386,08



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Door R R, Dent(s), Acceptable 0,00

No pictures to display