



MERCEDES A: 1GIL167

Vinnumber:	WDD1760111J244848	Versionname:	A 160 CDI 90PK
First Registrationdate:	17/02/2014	Fiscalpower:	
Expertise Mileage:	81588	Power Kw:	66
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1307
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	205/55/16/91 T LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 569,40

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Minor Damage and paint (complete) 244,00

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Dent(s), PDR - Paintless dent repair

63,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Dent(s), PDR - Paintless dent repair

82,80



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display