



BMW SERIE 2: 1KVN488

Vinnumber:	WBA2B31080V542868	Versionname:	216D ACTIVE TOURER
First Registrationdate:	14/07/2015	Fiscalpower:	
Expertise Mileage:	170716	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3104
Maintenance:	IN 9000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT		1032,52
-------------------	--	---------

Alloy rim R R, Scratch(es), Acceptable		0,00
--	--	------

No pictures to display

Ignition key, Missing, E - Replace		150,00
------------------------------------	--	--------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair	82,80
--	-------



Wing R L, Dent(s), It - Spot repair	115,56
-------------------------------------	--------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	259,80
---	--------



Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	283,80
---	--------



Interior, Not original part, P - Check	0,00
--	------



Seat cover F L, Stain, Acceptable	0,00
-----------------------------------	------

No pictures to display

Seat cover R, Stain, Acceptable	0,00
---------------------------------	------

No pictures to display

Seat cover F R, Stain, Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Boot carpet, Dirty, Cleaning	25,00
------------------------------	-------



Tires, Not original part, E - Replace 0,00



Wing F R, Scratch(es), It - Spot repair 115,56

