



FIAT 500: 1TFX795

Vinnumber:	ZFA3120000J880294	Versionname:	
First Registrationdate:	24/10/2017	Fiscalpower:	
Expertise Mileage:	24756	Power Kw:	62
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3428
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Sun Roof electric	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/45/16/84 V LightMetal			
Summer tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	670,68
--------------------------	---------------

Bumper F, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

No pictures to display

Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
---	--------



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	246,56
---	--------



Door F R, Scratch(es), LI - Repair and paint (complete)	254,68
---	--------

