


BMW 3: 1FQQ732

Vinnumber:	WBA3D11080J624657	Versionname:	3 BER 318d 136PK
First Registrationdate:	25/09/2013	Fiscalpower:	
Expertise Mileage:	108196	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2631
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK








Degree of wear

205/60/16/92 H LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Total cost ex VAT	1253,00
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20



Sill outer R, Scratch(es), It - Spot repair	115,56
	
Ignition key, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
	
Windscreen, Repaired, E - Replace	0,00
	
Sill outer L, Scratch(es), It - Spot repair	115,56
	
Seat cover F L, Damaged, Acceptable	0,00
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	