



HYUNDAI I30 5D: SF8545

Vinnumber:	TMAD351UAFJ253576	Versionname:	1.6 CRDI POP ISG
First Registrationdate:	27/05/2015	Fiscalpower:	
Expertise Mileage:	141615	Power Kw:	81
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4424
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4,5 mm	Re.R.	Continental: 4,5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1285,88
Alloy rim R L polished, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper F, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bodywork, Not original part, Remove lettering			0,00
<i>No pictures to display</i>			
Floor covering F L, Burned, Smart repair			64,32



Bumper R, Deformed / Strained, Le - Replace and paint 651,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Roof pillar R, Dent(s), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover R R, Tear, E - Replace 360,00



Door panel F L, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Acceptable 0,00

No pictures to display