


BMW 3 BERLINE: 1KFG990

Vinnumber:	WBA3E11040F560603	Versionname:	2.0 320D EFFICIENTDYN. (120KW) BERLINE
First Registrationdate:	21/04/2015	Fiscalpower:	
Expertise Mileage:	81002	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	FEBRUARI 2020	Parking lot:	3313
Maintenance:	2200		
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Rear parking sensors	
GPS storage	HD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			423,60
Door F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror basis L, Scratch(es), Acceptable			0,00

<i>No pictures to display</i>	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Maintenance book, Missing, Acceptable	0,00
<i>No pictures to display</i>	
Outer backrest protection L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror basis R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Outer backrest protection R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80

