


BMW 3: 1GUW956

Vinnumber:	WBA3D91030F406983	Versionname:	3 BER 316d 116PK
First Registrationdate:	7/05/2014	Fiscalpower:	
Expertise Mileage:	108968	Power Kw:	85
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2603
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 8 mm	Fr.R.	Michelin: 8 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1156,05
Foglight L, Broken, E - Replace			138,00



Roof, Scratch(es), 67 - Polish 0,00

No pictures to display

Roof pillar R, Scratch(es), Acceptable 0,00

No pictures to display


Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Scratch(es), LI - Repair and paint (complete) 0,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Dent(s), PDR - Paintless dent repair 63,00



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35

