


FORD Focus: 1HYE897

Vinnumber:	WF0LXXGCBLEM32569	Versionname:	FOCUS CLIP. ECONetic Trend 88g 105PK
First Registrationdate:	28/10/2014	Fiscalpower:	
Expertise Mileage:	151975	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4104
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H Steel			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT 1233,53

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper cover R M. Scratch(es). Smart repair 110,64



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F M, Scratch(es), Smart repair 110,64



Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Bumper grille, Broken, E - Replace 32,40



Bumper F, Bad repair, Acceptable 0,00



Rear window, Scratch(es), Acceptable 0,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover R R, Scratch(es), E - Replace

30,00



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display