


RENAULT CLIO: 1KNF402

Vinnumber:	VF15RJL0H52519222	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	2/06/2015	Fiscalpower:	
Expertise Mileage:	50427	Power Kw:	66
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4422
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 V Steel			
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1836,28

Bodywork, Not original part, Remove lettering 0,00

No pictures to display

Wing R R, Hail damage, PDR - Hail 25,00



Bonnet, Hail damage, PDR - Hail

150,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Wheel cover R L, Scratch(es), E - Replace

24,00



Wheel cover R R, Broken, E - Replace

24,00



Wheel cover F L, Scratch(es), E - Replace

24,00



Wheel cover F R, Broken, E - Replace

24,00



Roof, Hail damage, PDR - Hail

650,00



Wing R L, Hail damage, PDR - Hail

50,00

Wing R L, nail damage, PDR - nail

50,00



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

163,56



Roof pillar L, Hail damage, PDR - Hail

75,00



Interior, Stain, Cleaning

75,00



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete)

254,68



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar R, Hail damage, PDR - Hail

25,00



Door R R, Dent(s), PDR - Paintless dent repair

102,60



