



BMW 3: 1HJV537

Vinnumber:	WBA3Y11050D900828	Versionname:	3 GRAN TURISMO 318da 136PK Aut.
First Registrationdate:	5/08/2014	Fiscalpower:	
Expertise Mileage:	165626	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3515
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	143,00
-------------------	---------------

Door panel R R, Scratch(es), Acceptable	0,00
---	-------------

<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00

<i>No pictures to display</i>	
Foglight R, Crack, E - Replace	138,00



Seat cover R R, Incomplete, E - Replace	5,00
---	------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Steering wheel, Worn, Acceptable	0,00
----------------------------------	------

No pictures to display

Roof pillar L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------

No pictures to display

Bumper F, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display