



AUDI A4: 1HPN849

Vinnumber:	WAUZZZ8K0FA035435	Versionname:	A4 AVANT Ultra 136PK
First Registrationdate:	5/09/2014	Fiscalpower:	
Expertise Mileage:	180442	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4513
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	CD
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1955,59
Wing F R, Bad repair, Acceptable	0,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Floor covering F L, Hole, E - Replace 252,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00




Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Roof, Chemical polution, LI - Repair and paint (complete) 505,50



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Rear window, Scratch(es), Acceptable

0,00



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Tailgate, Bad repair, Acceptable

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bad repair, Acceptable 0,00



Bonnet, Dent(s), PDR - Paintless dent repair 142,20



Windscreen, Stone chip(s), Acceptable 0,00

