



AUDI A3: 1GIV539

Vinnumber:	WAUZZZ8V9E1026631	Versionname:	A3 SED Ambition S-tr.136PK Aut.
First Registrationdate:	19/02/2014	Fiscalpower:	
Expertise Mileage:	150062	Power Kw:	100
Bodytype:	Berline	Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3708
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Rear parking sensors	
GPS storage		Type of Tow bar	Tow bar removable
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	714,20
--------------------------	---------------

Door F R, Dent(s), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bonnet, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
Roof, Dent(s), PDR - Paintless dent repair	122,40
Windscreen, Stone chip(s), Acceptable	0,00
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

