



AUDI A3: 1GTK323

Vinnumber:	WAUZZZ8V4EA178686	Versionname:	A3 SB Attraction 136PK
First Registrationdate:	24/04/2014	Fiscalpower:	
Expertise Mileage:	184859	Power Kw:	100
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3610
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 949,03

Bumper grille, Deformed / Strained, E - Replace 32,40




Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35




Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Interior, Dirty, Cleaning

0,00



Sill outer R, Scratch(es), Acceptable

0,00

No pictures to display