



FORD FOCUS CLIPPER: 1NNA228

Vinnumber:	WF06XXGCC6GA02347	Versionname:	1.5 TDCI 88KW S/S BUSINESS EDITION
First Registrationdate:	22/03/2016	Fiscalpower:	
Expertise Mileage:	108286	Power Kw:	88
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4219
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3997,86
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Smart repair	110,64



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Tyre repair kit, Missing, E - Replace 210,53



Seat cover F R, Stain, Cleaning 25,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68





Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00




Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper spoiler F, Scratch(es), It - Spot repair 115,56



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00




Bumper corner R L, Scratch(es), Acceptable

0,00

No pictures to display

Floor covering F L, Burned, E - Replace

252,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Centre console, Hole, Smart repair

110,64



Bumper F, Deformed / Strained, LI - Repair and paint (complete)

211,80



Compressor, Missing, E - Replace

0,00



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00




Seat cover F L, Stain, Cleaning

25,00



Roof, Chemical pollution, LI - Repair and paint (complete)

481,50





Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08

