



**MERCEDES GLA: 1JXD415**

Vinnumber:	<b>WDC1569081J118863</b>	Versionname:	<b>2.1 GLA 200 CDI STYLE</b>
First Registrationdate:	<b>11/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>198058</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1431</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>1</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	<b>No Tow bar</b>
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/60/17/96 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Vredestein: 3 mm</b>	Fr.R.	<b>Vredestein: 3 mm</b>
	Re.L.	<b>Vredestein: 4 mm</b>	Re.R.	<b>Vredestein: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>370,88</b>
-------------------	---------------

Backrest cover F L, Worn, Acceptable	<b>0,00</b>
--------------------------------------	-------------



Door panel R R, Hole, Smart repair

110,64



Alloy rim F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bonnet, Stone chip(s), Acceptable

0,00

*No pictures to display*

Trunk lid covering R, Scratch(es), E - Replace

67,28



Backrest cover R L, Hole, Smart repair

64,32



Bumper F, Scratch(es), Acceptable

0,00

*No pictures to display*

Ceiling, Hole, Smart repair

64,32



Backrest cover R L, Damaged, Smart repair

64,32

