



**MERCEDES CLA: 1HZB455**

Vinnumber:	<b>WDD1173121N147205</b>	Versionname:	<b>CLA BER 180 CDI 109PK</b>
First Registrationdate:	<b>4/11/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>107334</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1123</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>1</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	<b>No Tow bar</b>
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Manual climate control</b>
Sport seats	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/45/17 91 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 8 mm</b>	Re.R.	<b>Continental: 8 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>Yes</b>
------------	-----------	------------	------------

Total cost ex VAT	<b>297,80</b>
Door panel F R, Hole, E - Replace	<b>114,00</b>



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Tyre repair kit, Missing, E - Replace 30,00



Alloy rim R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Bonnet, Stone chip(s), Acceptable 0,00

*No pictures to display*

Door F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Door F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Door R R, Dent(s), Acceptable 0,00

*No pictures to display*

Sill trim R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door panel F L, Worn, Acceptable 0,00



Windscreen, Stone chip(s), Windscreen repair 58,80

