



FORD Galaxy: 1JAG490

Vinnumber:	WF0MXXGBWMER04687	Versionname:	GALAXY Trend Style St/St DPF 115PK
First Registrationdate:	15/11/2014	Fiscalpower:	
Expertise Mileage:	179825	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Body color:	.
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	3713
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 Y LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	976,48
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Trunk lid covering R, Scratch(es), E - Replace

199,42



Bonnet, Chemical polution, Acceptable

0,00



Wing R R, Scratch(es), Acceptable

0,00



Door R L, Scratch(es), Acceptable

0,00



Wing F L, Dent(s), PDR - Paintless dent repair

63,00



Bumper F, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

358,50



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Luggage space cover, Missing, E - Replace

50,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Wing R L, Scratch(es), Acceptable

0,00



Bonnet, Scratch(es), Acceptable

0,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Outer door handle F R, Scratch(es), LI - Repair and paint (complete)

115,56

