



**MERCEDES C BREAK: 1KSC970**

Vinnumber:	<b>WDD2052361F207615</b>	Versionname:	<b>1.6 C 180 BLUETEC</b>
First Registrationdate:	<b>22/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>77924</b>	Power Kw:	<b>85</b>
Bodytype:		Body color	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color	<b>BRUIN</b>
Transmission:	<b>Back</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer	<b>Aluminium</b>
Maintenance	<b>285 DAGEN</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>2533</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage	<b>SD</b>	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**


<b>205/60/16/92 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Hankook: 7 mm</b>	Fr.R.	<b>Hankook: 7 mm</b>
	Re.L.	<b>Hankook: 7 mm</b>	Re.R.	<b>Hankook: 7 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 1532,68

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20





Rearlight R , Scratch(es), E - Replace

114,00



Roof pillar R, Dent(s), PDR - Paintless dent repair

63,00



Tyre repair kit, Missing, E - Replace

210,53

