



BMW X3: 1KJF258			
Vinnumber:	WBAWZ310600K95361	Versionname:	2.0 SDRIVE18D (100KW)
First Registrationdate:	11/05/2015	Fiscalpower:	
Expertise Mileage:	105658	Power Kw:	100
Bodytype:	SUV	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2730
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	225/60/17/99 V LightMetal		
	Fr.L.	Fr.R.	Pirelli: 6 mm
	Re.L.	Re.R.	Pirelli: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			702,32
Bumper R, Scratch(es), LI - Repair and paint (complete)			254,16





Interior, Dirty, Chemical cleaning

150,00



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Roof, Scratch(es), 67 - Polish

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Seat cover F L, Worn, Acceptable

0,00



Rearview mirror housing R, Broken, E - Replace

44,00

