



MINI : 1PCU597			
Vinnumber:	WMWXN110403B51622	Versionname:	1.5 ONE D
First Registrationdate:	7/06/2016	Fiscalpower:	
Expertise Mileage:	55888	Power Kw:	70
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4428
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
GPS storage	HD Luggage cover
GPS storage	
Windows electric F	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	175/65/15/84 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	756,30
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), PDR - Paintless dent repair	63,00



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Roof, Scratch(es), LI - Repair and paint (complete)	481,50
---	--------

