



MERCEDES CLA SHOOTING BRAKE: 1KLX356

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | WDD1179081N231465 | Versionname: | 2.1 CLA 200 CDI URBAN SHOOTING BRAKE |
| First Registrationdate: | 29/05/2015 | Fiscalpower: | |
| Expertise Mileage: | 78109 | Power Kw: | 100 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2632 |
| Maintenance: | B5 14JOURS | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 1 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|---------------------------------------|-----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | SD | Luggage cover | |
| GPS storage | | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining semi-artificial leather | | |
| Sport seats | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-------------------------|-------|-------------------------|
| 225/45/17/91 Y LightMetal | | | | |
| Summer tyres: | Fr.L. | Vredestein: 7 mm | Fr.R. | Vredestein: 6 mm |
| | Re.L. | Vredestein: 8 mm | Re.R. | Vredestein: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 309,50 |
|-------------------|---------------|

| | |
|-----------------------------------|-------------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|



Door R R, Scratch(es), Acceptable

0,00



Seat cover F L, Stain, Cleaning

25,00



Gear shift lever knob, Worn, Acceptable

0,00



Wing R L, Bad repair, P - Check

0,00



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Alloy rim F L, Scratch(es), Acceptable

0,00



Ceiling, Scratch(es), Smart repair

64,32



Alloy rim F R, Scratch(es), Acceptable

0,00

