



**MERCEDES CLA: 1HSC087**

Vinnumber:	<b>WDD1173121N139906</b>	Versionname:	<b>CLA BER 180 CDI 109PK</b>
First Registrationdate:	<b>18/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>110657</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2223</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Type of Tow bar
Radio multimedia	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-leather</b>
Type of climate control	<b>Manual climate control</b>
Sport seats	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/40/18/92 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 8 mm</b>	Fr.R.	<b>Continental: 8 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>Yes</b>
------------	-----------	------------	------------

Total cost ex VAT 730,73

Alloy rim F R polished, Scratch(es), E - Replace 235,20





Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Tyre repair kit, Missing, E - Replace 210,53

*No pictures to display*

Door F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Door R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Bad repair, Acceptable 0,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00

