



**AUDI A5 SPORTBACK: 1KXF147**

Vinnumber:	<b>WAUZZZ8TXGA006776</b>	Versionname:	<b>2.0 TDI 140KW S LINE</b>
First Registrationdate:	<b>22/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>155827</b>	Power Kw:	<b>140</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>5000</b>	Parking lot:	<b>1512</b>
Maintenance:	<b>462 DAGEN</b>		
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	<b>HD</b>	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Sport seats			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>245/40/18/93 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Dunlop: 6 mm</b>	Fr.R.	<b>Dunlop: 6 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>380,00</b>
-------------------	---------------

Sill trim R L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper cover R M, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Dashboard, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Tyre R R, Tear, Acceptable 0,00

No pictures to display

Interior, Not original part, Acceptable 0,00

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Sill trim R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Seat F L compl, Worn, Acceptable 0,00

No pictures to display

Bumper F, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	