


OPEL Movano 3300 MWB Med.High.Roof: 1EAK186

Vinnumber:	WOLMRFCBCCB030971	Versionname:	MOVANO 3300 B/F L2H2(E5)DPF 100PK
First Registrationdate:	3/10/2012	Fiscalpower:	
Expertise Mileage:	168240	Power Kw:	74
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK		
Maintenance:	GEEN MELDING		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
Windows electric F		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/65/16/107 T Steel				
Summer tyres:	Fr.L.	Michelin: 8 mm	Fr.R.	Michelin: 8 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	644,58
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Acceptable	0,00



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 217,56



Wheel cover F L, Broken, E - Replace 22,50



Seat cover R, Stain, Acceptable 0,00

No pictures to display

Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Tires, Not original part, Acceptable 0,00

No pictures to display

Seat cover F L, Worn, Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 22,50



Steering wheel, Worn, Acceptable 0,00

No pictures to display

Bodywork, Accident, P - Check 0,00



