



OPEL Corsa: 1GVK003

Vinnnumber:	W0L0SDL68E4184375	Versionname:	CORSA BER ecoFL.Enjoy St/St DPF 95PK
First Registrationdate:	12/05/2014	Fiscalpower:	
Expertise Mileage:	176059	Power Kw:	70
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2201
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

185/65/15/88 T LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	918,98
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Scratch(es), LI - Repair and paint (complete)	385,20



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

241,34



Wiper Blade R, Damaged, E - Replace

28,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44

