



**PEUGEOT 308 SW: 1KJV908**

Vinnumber:	<b>VF3LCBHXHFS121261</b>	Versionname:	<b>1.6 BLUEHDI 85KW S/S ALLURE</b>
First Registrationdate:	<b>18/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>159419</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4703</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Panoramic roof	
GPS storage	<b>HD</b>	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>Tow bar removable</b>
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather and alcantara</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Dunlop: 3 mm</b>	Fr.R.	<b>Dunlop: 3 mm</b>
	Re.L.	<b>Dunlop: 3 mm</b>	Re.R.	<b>Dunlop: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 743,00


Door F L, Dent(s), Acceptable 0,00

*No pictures to display*

Wing R R, Dent(s), Acceptable 0,00

*No pictures to display*

Door F R, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Stone chip(s), Windscreen repair 88,20



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80

