


**PEUGEOT 5008: 1FGZ775**

|                         |                          |              |   |
|-------------------------|--------------------------|--------------|---|
| Vinnumber:              | <b>VF30A9HD8DS127512</b> | Versionname: | <b>5008 e-HDi Active FAP BMP 115PK Aut.</b> |
| First Registrationdate: | <b>26/06/2013</b>        | Fiscalpower: |   |
| Expertise Mileage:      | <b>160901</b>            | Power Kw:    | <b>84</b>                                   |
| Bodytype:               |                          | Body color:  | <b>Grey</b>                                 |
| Gearbox:                | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                              |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                            |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                   |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>4233</b>                                 |
| Number of doors:        | <b>5</b>                 |              |   |
| Number of seats:        | <b>5</b>                 |              |   |
| Number head rests:      | <b>5</b>                 |              |   |
| Rims summer:            | <b>Aluminium</b>         |              |   |
| Category:               | <b>Passenger Car</b>     |              |   |
| Oil level:              | <b>OK</b>                |              |   |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Panoramic roof               |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 | Type of Tow bar              |
| Steering wheel multifunctional | <b>No Tow bar</b>            |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/55/16/95 V LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|               | Re.L.                            | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|  |            |      |            |
|--|------------|------|------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|   |        |
|---|--------|
| Total cost ex VAT                                       | 306,80 |
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 211,80 |



|  |       |
|--|-------|
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|                               |      |
|-------------------------------|------|
| Tailgate, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*