



AUDI A4: 1JTX036

Vinnnumber:	WAUZZZ8K7FN030970	Versionname:	
First Registrationdate:	24/02/2015	Fiscalpower:	100
Expertise Mileage:	151554	Power Kw:	White
Bodytype:	Berline	Body color:	Opaque
Gearbox:	MAN 6 VIT	Paint type:	Aluminium
Transmission:	Front	Rims summer:	OK
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4230
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Rear parking sensors
GPS storage	CD
Windows electric F	Type of Tow bar
Windows electric R	Tow bar removable
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	995,80
Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20



Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door seal F L, Deformed / Strained, Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Chemical pollution, 67 - Polish	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Door R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Hole, E - Replace	74,00



Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

