



**AUDI A3 SPORTBACK: 1LUN635**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber:                         | <b>WAUZZZ8V5FA119941</b> | Versionname: | <b>2.0 TDI 100KW S TRONIC AMBIENTE</b> |
| First Registrationdate:            | <b>7/09/2015</b>         | Fiscalpower: |  |
| Expertise Mileage:                 | <b>81346</b>             | Power Kw:    | <b>100</b>                             |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Silver</b>                          |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metallic</b>                        |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                       |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                              |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3402</b>                            |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>5</b>                 |              |  |
| Number head rests:                 | <b>5</b>                 |              |  |
| Rims summer:                       | <b>Aluminium</b>         |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                                |                              |                   |
|--------------------------------|------------------------------|-------------------|
| Radio CD                       | Sun Roof electric            |                   |
| Windows electric F             | Central consol F             |                   |
| Windows electric R             | Luggage cover                |                   |
| Cruise Control                 | Front parking sensors        |                   |
| Steering wheel multifunctional | Rear parking sensors         |                   |
| Seats F heated                 | Type of Tow bar              | <b>No Tow bar</b> |
| Radio multimedia               |                              |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                   |
| Type of Lining                 | <b>Lining leather</b>        |                   |
| Type of climate control        | <b>Autom climate control</b> |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>205/55/16/91 W LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>Continental: 4 mm</b> | Fr.R. | <b>Continental: 4 mm</b> |
|                                  | Re.L. | <b>Continental: 4 mm</b> | Re.R. | <b>Continental: 4 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|   |               |
|---|---------------|
| <b>Total cost ex VAT</b>  | <b>676,60</b> |
| <b>Alloy rim F R, Scratch(es), LI - Repair and paint (complete)</b> | <b>95,00</b>  |



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door F R, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80

