



BMW 3 GRAN TURISMO: 1KDS734

Vinnumber:	WBA3Y11010GD87613	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	9/04/2015	Fiscalpower:	
Expertise Mileage:	75831	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 7000 KM	Parking lot:	4732
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Fr.R.	Michelin: 5 mm
	Re.L.	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 682,40

Bonnet, Dent(s), PDR - Paintless dent repair 82,80



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (partial)

211,80



Door R L, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (partial)

229,80

