



BMW 1 HATCH: 1PHJ263

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | WBA1V910305D73626 | Versionname: | 1.5 116D EFFICIENTDYNAMICS EDIT. (85KW) |
| First Registrationdate: | 6/07/2016 | Fiscalpower: | |
| Expertise Mileage: | 50854 | Power Kw: | 85 |
| Bodytype: | Hatchback | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metallic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2413 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | Type of Tow bar |
| Radio multimedia | No Tow bar |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | |
|----------------------------------|-------|-------|-----------------------|
| 205/55/16/91 H LightMetal | | | |
| Summer tyres: | Fr.L. | Fr.R. | Semperit: 6 mm |
| | Re.L. | Re.R. | Semperit: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-----------------------------------|---------------|
| Total cost ex VAT | 558,00 |
| Tailgate, Scratch(es), Acceptable | 0,00 |

No pictures to display

| | |
|-------------------------------|---------------|
| Roof, Hail damage, PDR - Hail | 400,00 |
|-------------------------------|---------------|



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Rear window, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s), PDR - Paintless dent repair

63,00



Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), 67 - Polish

0,00

No pictures to display