



BMW 5: 1HYK060

Vinnumber:	WBA5E31030D786616	Versionname:	5 BER 518dA 136PK Aut.
First Registrationdate:	29/10/2014	Fiscalpower:	
Expertise Mileage:	56149	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 29000 KM	Parking lot:	2305
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1370,32

Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Roof, Chemical polution, LI - Repair and paint (complete)

577,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), 67 - Polish

0,00

No pictures to display

Wing R L, Bad repair, P - Check

0,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Mirror side blinker L, Broken, E - Replace

31,20



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Door frame R L, Dent(s), Acceptable

0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16





Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Door F R, Scratch(es), 67 - Polish

0,00

No pictures to display