


RENAULT Kangoo Express: 1GTF487

Vinnumber:	VF1FW17B550570647	Versionname:	KANGOO EXPRESS B/F Extra 75PK
First Registrationdate:	23/04/2014	Fiscalpower:	
Expertise Mileage:	45219	Power Kw:	55
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4207
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	No climate control		

Limited Technical Inspection

Tires wear profile	OK	Battery functioning	Yes
Idle position	OK	Power steering	Yes
Engine startingtime	OK	Sound engine	OK
Exhaust gass	OK	Clutch test	OK
Handbrake	OK	Wiper fluid level	OK
		Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 T Steel				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1851,58
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R L, Hole, E - Replace	91,50



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R L, Dent(s) and scratch(es), It - Spot repair 115,56



Bumper F, Scratch(es), Smart repair 110,64



Bumper moulding R R, Scratch(es), Smart repair 110,64



Internal Boot Lining L, Hole, Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, Acceptable 0,00

No pictures to display

Rearview mirror L complete, Broken, E - Replace 138,00





Windscreen, Stone chip(s), E - Replace

0,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Bumper R, Scratch(es), Smart repair

110,64




Trunk door R R, Dent(s) and scratch(es), It - Spot repair

115,56



Roof, Dent(s), LI - Repair and paint (complete)

361,13



Door moulding Lower R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Glove compartment lid, Broken, E - Replace 228,00

