


RENAULT SCENIC: 1KLC557

Vinnumber:	VF1JZ14K653061736	Versionname:	1.5 ENERGY DCI 110 LIFE
First Registrationdate:	26/05/2015	Fiscalpower:	
Expertise Mileage:	124650	Power Kw:	81
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2309
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H Steel			
Winter tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	1354,80
Wheel cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Hole, E - Replace	360,00



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Seat cover R L, Hole, E - Replace 360,00



Roof pillar R, Dent(s), PDR - Paintless dent repair 63,00



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover R L, Hole, E - Replace 360,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display