



VOLKSWAGEN Golf: 1GWET29

Vinnnumber:	WVWZZZAUZEP597013	Versionname:	GOLF VAR Trendline DSG 105PK Aut.
First Registrationdate:	16/05/2014	Fiscalpower:	
Expertise Mileage:	157145	Power Kw:	77
Bodytype:		Body color:	.
Gearbox:	Automatic	Body color:	Grey
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Steel
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	4118
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1116,83

Wing F L, Dent(s), PDR - Paintless dent repair 63,00



Wheel cover F R, Scratch(es), Acceptable

0,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Wing F R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Roof, Scratch(es), Acceptable

0,00



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Backrest cover F L, Worn, Acceptable

0,00



Door F L, Dent(s), PDR - Paintless dent repair

63,00



Door R L, Dent(s), LI - Repair and paint (complete)

414,35

