



**RENAULT CLIO GRANDTOUR: 1KRP767**

Vinnumber:	<b>VF17R040H53216690</b>	Versionname:	<b>1.5DCI 75 EXPRESSION</b>
First Registrationdate:	<b>17/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>43359</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4604</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/88 T Steel</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 6 mm</b>	Fr.R.	<b>Goodyear: 6 mm</b>
	Re.L.	<b>Goodyear: 6 mm</b>	Re.R.	<b>Goodyear: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

<b>Total cost ex VAT</b>	<b>758,40</b>
--------------------------	---------------

<b>Bonnet, Stone chip(s), Acceptable</b>	<b>0,00</b>
--	-------------

*No pictures to display*

<b>Windscreen, Stone chip(s), Acceptable</b>	<b>0,00</b>
--	-------------

*No pictures to display*

<b>Bumper corner R R, Dent(s), Acceptable</b>	<b>0,00</b>
---	-------------

*No pictures to display*

No pictures to display

Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair

110,64



Door F L, Dent(s), PDR - Paintless dent repair

63,00



Spoiler R, Scratch(es), LI - Repair and paint (complete)

115,56



Wheel cover F R, Scratch(es), E - Replace

24,00



Bumper spoiler F, Deformed / Strained, E - Replace

36,00



Wheel cover F L, Scratch(es), E - Replace

24,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 385,20

