



**VOLVO XC60: 1KRJ361**

Vinnumber:	<b>VV1DZARC1G2783533</b>	Versionname:	<b>2.0 D3 2WD MOMENTUM</b>
First Registrationdate:	<b>16/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>133884</b>	Power Kw:	<b>110</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4832</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/65/17/104 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>474,16</b>
Alloy rim F L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wing R R, Dent(s), PDR - Paintless dent repair	<b>63,00</b>



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Door panel R L, Tear, E - Replace	132,00
-----------------------------------	--------



Wing R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Boot carpet, Stain, Cleaning	25,00
------------------------------	-------



Internal Boot Lining R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door panel F L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Roof, Rust, LI - Repair and paint (complete)	0,00
--	------

