


SKODA Superb: 1HBD854

Vinnumber:	TMBJJ73T8E9059476	Versionname:	SUPERB COMBI Elegance 105PK
First Registrationdate:	10/06/2014	Fiscalpower:	
Expertise Mileage:	139163	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2702
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Seats F L ventilated	
Windows electric F		Seats F R ventilated	
Windows electric R		Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Central consol F	
Seats F heated		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting Xenon	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar removable
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/91 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1525,36
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Dent(s), PDR - Paintless dent repair

63,00



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display


Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete)

382,02



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display