



VOLVO V60: 1NLY507

Vinnumber:	YV1FW78C0G1321192	Versionname:	2.0 D2 GEARTRONIC MOMENTUM
First Registrationdate:	22/03/2016	Fiscalpower:	
Expertise Mileage:	175257	Power Kw:	88
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2825
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	Tow bar fixed
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/50/17/95 W LightMetal			
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT	1090,80
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00





Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s), Acceptable

0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing L, Broken, E - Replace

74,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80

