



**VOLKSWAGEN Passat: 1HRE477**

Vinnumber:	<b>WVWZZZ3CZFE049347</b>	Versionname:	<b>PASSAT VAR Comfortline BMT DSG 105PK Aut</b>
First Registrationdate:	<b>11/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>151818</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4715</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Laser</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/55/16/97 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 7 mm</b>	Fr.R.	<b>Uniroyal: 7 mm</b>
	Re.L.	<b>Dunlop: 6 mm</b>	Re.R.	<b>Dunlop: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	2066,17
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80





Wing R R, Scratch(es), LI - Repair and paint (complete)

0,00



Door frame F L, Dent(s), It - Spot repair

115,56



Backrest cover F L, Damaged, E - Replace

360,00




Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display


Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Tailgate, Scratch(es), 67 - Polish

0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35

