



VOLVO XC60: 1GAI315

Vinnumber:	YV1DZ31A1E2564899	Versionname:	XC60 D3 Kinetic 136PK
First Registrationdate:	5/12/2013	Fiscalpower:	
Expertise Mileage:	190559	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4327
Maintenance:	OVER 18473KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/108 H LightMetal			
Winter tyres:	Fr.L.	Fulda: 7 mm	Fr.R.	Fulda: 7 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------







Total cost ex VAT	1198,08
-------------------	---------

Roof pillar R, Dent(s), Acceptable	0,00
------------------------------------	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Sill outer L, Deformed / Strained, Le - Replace and paint	0,00
	
Alloy rim F L polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door moulding Lower R L, Missing, E - Replace	0,00
	
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door moulding Lower F L, Dent(s) and scratch(es), E - Replace	0,00
	
Door F L, Dent(s) and scratch(es), Le - Replace and paint	1082,52
	
Bumper F R, Scratch(es), It - Spot repair	115,56
	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	