



VOLKSWAGEN Crafter 35 MWB hoog dak: 1HCL254

Vinnumber:	WV1ZZZ2EZE6035874	Versionname:	TDI
First Registrationdate:	18/06/2014	Fiscalpower:	
Expertise Mileage:	170287	Power Kw:	120
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	TRU17
Maintenance:	IN 26700 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F
GPS storage		
Windows electric F		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/16/115 R Steel			
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1056,50
Bumper F, Dent(s) and scratch(es), E - Replace	398,40





Interior, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Trunk door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sidewall RL (LCV), Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing trim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Central pillar R, Deformed / Strained, LI - Repair and paint (complete)	213,14



Maintenance book, Missing, E - Replace	0,00
--	------



Interior, Not original part, P - Check	0,00
--	------



Door R R, Dent(s) and scratch(es), It - Spot repair	115,56
---	--------



Door trim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Separation wall, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Remove lettering	0,00



Ignition key, Broken, E - Replace	150,00
-----------------------------------	--------



Door hinge R L bottom, Damaged, E - Replace	87,90
---	-------



Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, P - Check	0,00



Rearlight L, Broken, E - Replace

91,50



Instruction book, Missing, E - Replace

0,00

No pictures to display

Bumper corner R L, Scratch(es), E - Replace

0,00

