



**VOLVO XC60: 1FMQ018**

|                                    |                          |              |   |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber:                         | <b>YV1DZ31A1E2514850</b> | Versionname: | <b>XC60 D3 Kinetic Start/Stop 136PK</b> |
| First Registrationdate:            | <b>21/08/2013</b>        | Fiscalpower: |   |
| Expertise Mileage:                 | <b>174808</b>            | Power Kw:    | <b>100</b>                              |
| Bodytype:                          | <b>SUV</b>               | Body color:  | <b>Grey</b>                             |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metallic</b>                         |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                        |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                               |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2108</b>                             |
| Number of doors:                   | <b>5</b>                 |              |   |
| Number of seats:                   | <b>5</b>                 |              |   |
| Number head rests:                 | <b>5</b>                 |              |   |
| Rims summer:                       | <b>Aluminium</b>         |              |   |
| Category:                          | <b>Passenger Car</b>     |              |   |
| Oil level:                         | <b>OK</b>                |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |   |

**Options**

|                                |                              |                      |                   |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD                       |                              | Central consol F     |                   |
| GPS storage                    | <b>HD</b>                    | Luggage cover        |                   |
| GPS storage                    |                              | Rear parking sensors |                   |
| Windows electric F             |                              | Type of Tow bar      | <b>No Tow bar</b> |
| Windows electric R             |                              |                      |                   |
| Cruise Control                 |                              |                      |                   |
| Steering wheel multifunctional |                              |                      |                   |
| Radio multimedia               |                              |                      |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                   |
| Type of Lining                 | <b>Lining leather</b>        |                      |                   |
| Type of climate control        | <b>Autom climate control</b> |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                   |                       |       |                       |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
|               | <b>235/65/17/108 V LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                             | <b>Uniroyal: 2 mm</b> | Fr.R. | <b>Uniroyal: 2 mm</b> |
|               | Re.L.                             | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|  |                |
|--|----------------|
| <b>Total cost ex VAT</b>                     | <b>1077,98</b> |
| <b>Windscreen, Stone chip(s), Acceptable</b> | <b>0,00</b>    |



Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair 82,80



Door moulding Lower F R, Tear, E - Replace 132,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16





Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door moulding Lower R R, Dent(s) and scratch(es), E - Replace

132,00



Door F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper F, Scratch(es), Acceptable

0,00

*No pictures to display*