


PEUGEOT 208: 1GIL155

Vinnumber:	VF3CC9HP8ET025516	Versionname:	208 BER e-HDi Active BMP STT 92PK Aut.
First Registrationdate:	17/02/2014	Fiscalpower:	
Expertise Mileage:	97953	Power Kw:	68
Bodytype:	Hatchback	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4515
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Central consol F	
Steering wheel multifunctional		Luggage cover	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/65/15/88 T Steel				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1023,80
Protection plate M, Tear, E - Replace			74,00


Wheel cover R R, Scratch(es), E - Replace
24,00



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Roof, Hail damage, PDR - Hail 0,00



Wheel cover F R, Deformed / Strained, E - Replace 24,00



Rocker panel inner F L, Dent(s), LI - Repair and paint (complete) 115,56



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Dent(s), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 246,56



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68

