


OPEL Movano 3500 MWB Med.High Roof: 1GFI406

Vinnumber:	WOLMRFESCEB049677	Versionname:	MOVANO 3500 B/F L2H2 ecoFL.(E5)125PK
First Registrationdate:	23/01/2014	Fiscalpower:	
Expertise Mileage:	122483	Power Kw:	92
Bodytype:	Transporter	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV30
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Type of Tow bar	No Tow bar
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/65/16/112 R Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	980,67
-------------------	--------

Tailgate, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Dent(s) and scratch(es), Acceptable	0,00
-------------------------------------	------

Door trim R R, Dent(s) and scratch(es), E - Replace

91,50



Door F R, Dent(s), PDR - Paintless dent repair

63,00



Wing R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wing trim R R, Missing, E - Replace

69,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete)

526,02



Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Scratch(es), E - Replace

0,00



Bodywork, Not original part, Acceptable

0,00

No pictures to display