



VOLKSWAGEN Transporter: 1BDD363

| | | | |
|------------------------------------|---------------------------------|--------------|---------------------------------|
| Vinnumber: | WV1ZZZ7HZBH117362 | Versionname: | TRANSP.800 B/F SWB 102PK |
| First Registrationdate: | 5/05/2011 | Fiscalpower: | |
| Expertise Mileage: | 260826 | Power Kw: | 75 |
| Bodytype: | Transporter | Body color: | White |
| Gearbox: | MAN 5 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4116 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Light Commercial Vehicle | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|-------------------------|-------------------------------|-----------------|----------------------|
| Radio multimedia | | Type of Tow bar | Tow bar fixed |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | No GPS | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|------------------------------|--------------------------|-------|--------------------------|
| | 205/65/16/105 T Steel | | | |
| Summer tyres: | Fr.L. | Continental: 2 mm | Fr.R. | Continental: 2 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (normal) | 0 |
| Number of charging cables (rapid charge) | 0 |

| | |
|--------------------------|----------------|
| Total cost ex VAT | 1310,75 |
|--------------------------|----------------|

| | |
|--|-------------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|--|-------------|

No pictures to display

| | |
|---|---------------|
| Bonnet, Rust, LI - Repair and paint (complete) | 217,56 |
|---|---------------|



| | |
|--|-------------|
| Sliding door R, Dent(s), Acceptable | 0,00 |
|--|-------------|

No pictures to display

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)

231,15



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,88



Roof, Dent(s), Acceptable

0,00

No pictures to display

Sill outer L, Rust, LI - Repair and paint (complete)

232,88



Wing F L, Rust, LI - Repair and paint (complete)

165,13



Wing R L, Scratch(es), LI - Repair and paint (complete)

231,15



Tailgate, Dent(s), Acceptable

0,00

No pictures to display